

First floor preparations underway and new footings in place for slab foundation.





Replacement structural support beams and posts installed.





Installation of site drainage and sewer improvements underway.





Ole Hanson Beach Club Rehabilitation April-June

Pool systems improvements underway.









Second floor elevator location being prepared.



First floor interior plumbing installation underway.





Restoration of exterior architectural elements underway.



